

| Ref # | Hits | Search Query  | DBs   | Default Operator | Plurals | Time Stamp       |
|-------|------|---|---|------------------|---------|------------------|
| L1    | 18   | ((aircraft or airplane) near5 (repair or repairing)) and (touch near2 screen)                       | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:15 |
| L2    | 15   | ((on-site) near5 (repair or repairing)) and (touch near2 screen)                                    | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:07 |
| L3    | 351  | (video near3 display) and (repair or repairing) and (touch near2 screen)                            | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:08 |
| L4    | 51   | (video near3 display) and (repair or repairing) and (aircraft or airplane) and (touch near2 screen) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:08 |
| L5    | 6    | ((vacuum near2 repair)) and (thermocouple)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:09 |
| L6    | 0    | (curing and maintenance) and ("156"/\$.ccls.) and (touch near2 screen)                              | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 20:16 |
| L7    | 1    | (curing and repair) and ("156"/\$.ccls.) and (touch near2 screen)                                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 21:03 |
| L8    | 0    | (curing and repair) and ("264"/\$.ccls.) and (touch near2 screen)                                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/01/13 21:13 |

|     |     |  |   |    |     |                  |
|-----|-----|--|---|----|-----|------------------|
| L9  | 7   | portable and (curing near3 device) and (touch near2 screen)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 21:14 |
| L10 | 60  | portable and (heating near3 device) and (touch near2 screen)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 21:15 |
| S1  | 1   | ("20040177928").PN.  | US-PGPUB  | OR | OFF | 2005/01/10 19:04 |
| S2  | 503 | (156/359).CCLS.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/11 13:24 |
| S3  | 1   | ("6018614").PN.  | USPAT   | OR | OFF | 2005/01/10 19:21 |
| S4  | 9   | ("3681567"   "4081238"  <br>"4244349"   "4313417"   "4517038"<br>  "4652319"   "5078821"  <br>"5374388"   "5922227").PN.   | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2005/01/10 19:05 |
| S5  | 2   | ("6018614").URPN.  | USPAT   | OR | ON  | 2005/01/10 19:05 |
| S6  | 38  | ("0432205"   "1313258"  <br>"1534042"   "3324625"   "3694625"<br>  "4011430"   "4024378"  <br>"4147923"   "4189093"   "4195415"<br>  "4286391"   "4302663"  <br>"4405855"   "4447712"   "4510369"<br>  "4559441"   "4625096"  <br>"4734872"   "4812622"   "4920252"<br>  "4991377"   "5019994"  <br>"5021637"   "5123477"   "5205132"<br>  "5207379"   "5280422"  <br>"5308958"   "5367787"   "5394623"<br>  "5494097"   "5671321"  <br>"5682684"   "6018614").PN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2005/01/10 19:10 |
| S7  | 105 | portable near2 (cure or curing or curer)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 19:56 |
| S8  | 396 | portable and ((cure or curing or curer) and vacuum and heater)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/11 16:43 |

|     |     |   |   |    |     |                  |
|-----|-----|---|---|----|-----|------------------|
| S9  | 0   | portable and ((cure or curing or curer) and vacuum and heater) and "156"/\$.ccls,                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/10 19:18 |
| S10 | 37  | portable and ((cure or curing or curer) and vacuum and heater) and "156"/\$.ccls.                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/10 19:19 |
| S11 | 5   | portable and ((cure or curing or curer) and vacuum and heater) and "392"/\$.ccls.                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/10 19:20 |
| S12 | 1   | portable and ((cure or curing or curer) and vacuum and heater) and "432"/\$.ccls.                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/10 19:20 |
| S13 | 17  | portable and ((cure or curing or curer) and vacuum and heater) and "219"/\$.ccls.                   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/10 19:20 |
| S14 | 1   | ("4352707").PN.   | USPAT   | OR | OFF | 2005/01/10 19:21 |
| S15 | 11  | ("2123549"   "3033298"   "3837965"   "3951724"   "3996091"   "4140050"   "4162393"   "4279255").PN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2005/01/10 19:21 |
| S16 | 31  | ("3837965").URPN.   | USPAT   | OR | ON  | 2005/01/10 19:21 |
| S17 | 27  | ("4352707").URPN.   | USPAT   | OR | ON  | 2005/01/10 19:23 |
| S18 | 780 | (156/378).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/13 18:21 |
| S19 | 223 | (156/379).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:13 |

|     |     |   |   |    |     |                  |
|-----|-----|---|---|----|-----|------------------|
| S20 | 8   | (portable near2 (repair or repairing)) and (vacuum and heater)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/11 17:41 |
| S21 | 104 | (portable near2 (repair or repairing or vacuum or heat or heater or heating)) and (LCD or (touch near2 screen)) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/11 17:43 |
| S22 | 90  | (portable near2 (vacuum or heat or heater or heating)) and (LCD or (touch near2 screen))                        | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/11 17:43 |
| S23 | 411 | (156/358).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 20:00 |
| S24 | 2   | ((vacuum near2 bag) same repair) and (LCD or (touch near2 screen))  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 22:26 |
| S25 | 14  | ((vacuum near2 bag) same repair) and portable   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 19:58 |
| S26 | 269 | (156/360).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 20:58 |
| S27 | 54  | ((vacuum near2 bag)) and (LCD or (touch near2 screen))  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 22:20 |

|     |      |  |   |    |     |                  |
|-----|------|--|---|----|-----|------------------|
| S28 | 1124 | (156/94).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:09 |
| S29 | 385  | (156/98).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:17 |
| S30 | 1    | (S29 or S28) and (repair or repairing) and (LCD or (touch near2 screen)) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 20:59 |
| S31 | 2    | (S29 or S28) and (LCD or (touch near2 screen))                           | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:03 |
| S32 | 39   | (on-site near3 repair) and (LCD or (touch near2 screen))                 | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:13 |
| S33 | 2    | 29/402.\$.ccls. and (vacuum) and (LCD or (touch near3 screen))           | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:09 |
| S34 | 1    | 29/402.\$.ccls. and (heater) and (LCD or (touch near3 screen))           | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:09 |
| S35 | 7    | 29/402.\$.ccls. and (LCD or (touch near3 screen))                        | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:09 |

|     |     |   |   |    |     |                  |
|-----|-----|---|---|----|-----|------------------|
| S36 | 238 | (29/402.01).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:18 |
| S37 | 137 | (29/402.21).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:18 |
| S38 | 63  | (264/36.1).CCLS.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:17 |
| S39 | 94  | (264/36.17).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:18 |
| S40 | 269 | (156/381).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/12 21:18 |
| S41 | 4   | S40 and (LCD or (touch near2 screen))                     | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 21:13 |
| S42 | 3   | ((vacuum near2 repair)) and (LCD or (touch near2 screen)) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 20:09 |
| S43 | 0   | ((vacuum near2 repair)) and (portable near3 computer)     | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 22:21 |

|     |     |   |   |    |     |                  |
|-----|-----|---|---|----|-----|------------------|
| S44 | 10  | ((vacuum near2 bag)) and<br>(portable near3 computer) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 22:21 |
| S45 | 0   | ((vacuum near2 bag) same repair)<br>and (laptop)      | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/12 22:26 |
| S46 | 1   | ((vacuum near2 bag) and repair)<br>and (laptop)       | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 11:23 |
| S47 | 3   | (portable near2 repair) and (laptop)                  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 11:24 |
| S48 | 11  | (portable near2 repair) and (touch<br>near2 screen)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON  | 2005/01/13 20:01 |
| S49 | 443 | (156/351).CCLS.                                       | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/01/13 18:21 |